REPÚBLICA DOMINICANA
INSTITUTO DOMINICANO DE AVIACIÓN CIVIL
SERVICIOS DE INFORMACIÓN AERONÁUTICA

Apartado Postal 1180, Santo Domingo, D. N., Tel. (809) 542-0160, 221-7909, 549-0402, FAX (809) 221-8616, 549-0692

AIS DOMINICAN REPUBLIC **WEB SITE : www.aip.idac.gov.do** **AFTN : MDSDYNYX** **E-MAIL : ais@idac.gov.do** **pub@idac.gov.do**	IDAC INSTITUTO DOMINICANO DE AVIACIÓN CIVIL	**Monthly list of valid NOTAM** **AUG 06-10**

THE FOLLOWING NOTAM SERIE "A" STILL IN FORCE AT 1007312359

2010:	**0012**	**0013**	**0015**	**0222**	**0234**	**0241**	**0242**	**0245**	**0247**
0250	**0251**	**0259**	**0260**	**0261**	**0287**	**0297**	**0298**	**0305**	**0308**
0319	**0320**								

AIS INTEGRATED PACKAGE: LATEST PUBLICATIONS

AIP REGULAR AMDT	**MAY-30-2010** **NOV-30-2009**	**NIL** **4-09**
AIP AIRAC AMDT	**JUL-29-10**	**2-10**
AIRAC EFFECTIVE DATES	**AUG-26-2010** **SEP-23-2010**	**NIL** **NIL**
CURRENT AIP/ SUP:		**2009**
GEN :		**NIL**
ENR :		**NIL**
AD:	**NOV-05-2009**	**A01-09**
CURRENT/AIC:		**2008**
GEN:	**AUG-04-2008** **NOV-27-2008**	**No. 02-08** **No. 05-08**
ENR:	**MAR-20-2010** **NOV-27-2008** **NOV-27-2008**	**No. 01-10** **No. 03-08** **No. 04-08**
AD:	**NOV-27-2008**	**No. 04-08**
Monthly list of valid NOTAM:	**AUG-06-2010**	**AUG**

NR	Date	TEXT
A0012-10	**10-01-12**	**MDBH / MARIA MONTEZ INT'L AP** **1001121445/PERM** BHO VOR ON FREQUENCY 112.0 Mhz UNSERVICEABLE.
A0013-10	**10-01-12**	**MDBH / MARIA MONTEZ INT'L AP** **1001121450/PERM** MARIA MONTEZ INTERNATIONAL AIRPORT OPERATING FROM SUNRISE TO SUNSET.
A0015-10	**10-01-12**	**MDBH / MARIA MONTEZ INT'L AP** **1001121450/PERM** AERODROME OPERATING LIMITED TO VISUAL FLIGHT RULES ONLY.
A0222-10	**10-05-21**	**MDBH / MARIA MONTEZ INT'L AP** **1005211850/PERM** BHO DME ON FREQUENCY 112.0 Mhz UNSERVICEABLE.

NR	Date	TEXT
A0234-10	**10-05-27**	**MDPC / PUNTA CANA INT'L AP** **1005271720/PERM** RUNWAY 09 FRICTION COEFFICIENT IN THE FIRST THIRD MEASURED BELOW THE LEVEL SPECIFIED IN CIRCULAR CA 1400-03, PART 11.2.6, NUM (3), WILL BE CONSIDERED SLIPPERY SURFACE WHEN WET, CAUTION IS ADVISED, A COPY OF THIS CIRCULAR MAY BE DOWNLOADED FROM: **HTTP://WWW.IDAC.GOV.DO./SEGURIDADOPE/CIRCULARES.HTM**
A0241-10	**10-06-02**	**MDSI / SAN ISIDRO INT'L AP** **1006021800/1009021800 EST** SIS VOR ON FREQUENCY 114.5 Mhz ON TEST.
A0242-10	**10-06-03**	**MDSD / LAS AMERICAS INT'L AP** **1006031500/1008301059** AIRCRAFT STAND FROM C -1 TO C -13 LIMITED ACCESS AND EXIT FOR THE FOLLOWING AIRCRAFT TO STAR UP: B-777, B-767, B-757, B-747, B-737, B-707, A-340, A-320, A-319, A-310, A-300, DC-8, DC-10, E-190 AND E-145 DUE TO MEN AND EQUIPMENT WORKING.
A0245-10	**10-06-07**	**MDCY / EL CATEY INT'L AP** **1006071945/1008072359 EST** DCY DME ON FREQUENCY 115.8 Mhz UNSERVICEABLE DUE TO MAINTENANCE.
A0247-10	**10-06-10**	**MDBH / MARIA MONTEZ INT'L AP** **1006101600/1009100000** FIRE AND RESCUE SERVICES DOWNGRADED TO CAT-3.
A0250-10	**10-06-13**	**MDBH / MARIA MONTEZ INT'L AP** **1006131200/1009131200** FUEL AVIATION GASOLINE 100 NOT AVAILABLE.
A0251-10	**10-06-13**	**MDBH / MARIA MONTEZ INT'L AP** **1006131200/1009131200** FUEL JET A1 NOT AVAILABLE.
A0259-10	**10-06-23**	**MDLR / LA ROMANA INT'L AP** **1006232300/1009232200** RUNWAY END IDENTIFIER LIGHT 29 UNSERVICEABLE DUE TO MAINTENANCE.
A0260-10	**10-06-24**	**MDCS / SANTO DOMINGO FIR** **1006242100/1008242359** TO AVOID UNNECESSARY SEARCH AND RESCUE MISSIONS, AND DUE TO LIMITED COM COVERAGE OF THE PORT AU PRINCE ATC FACILITIES, ALL VISUAL FLIGHT RULES FLYING FROM SANTO DOMINGO FIR INTO PORT AU PRINCE FIR, MUST CANCEL FILED FLIGHT PLAN CROSSING THE BOUNDARY WITH SANTO DOMINGO FLIGHT INFORMATION CENTRE ON FREQUENCY 126.9 SANTO DOMINGO AREA CONTROL CENTRE FREQUENCY 124.3 OR 127.8 Mhz AND IF NOT POSSIBLE IN ANY OF THE ABOVE FREQUENCIES, CALL BARAHONA CONTROL TOWER ON FREQUENCY 118.5 OR CALL SANTO DOMINGO FLIGHT INFORMATION CENTRE VIA TEL + 1809-549-1310 EXT 355.
A0261-10	**10-06-25**	**MDSD / LAS AMERICAS INT'L AP** **1006251700/1008251700** TWY E-1 CLOSED FROM APRON TO TWY J DUE TO MEN AND EQUIPMENT WORKING.
A0287-10	**10-07-15**	**MDST / SANTIAGO INT'L AP** **1009200200/1009301100** **DAILY BETWEEN 0200-1100** RUNWAY 11/29 CLOSED DUE TO MEN AND EQUIPMENT WORKING.

NR	Date	TEXT
A0297-10	**10-07-19**	**MDCY / EL CATEY INT'L AP** **1007191730/1009012359** FUEL AVIATION GASOLINE 100/130 NOT AVAILABLE.
A0298-10	**10-07-19**	**MDPC / PUNTA CANA INT'L AP** **1007192000/1009161200** NEW RUNWAY UNDER CONSTRUCTION, WORK IN PROGRESS AT 760 METRES NORTH OF RUNWAY 09/27.
A0305-10	**10-07-21**	**MDCS / SANTO DOMINGO FIR** **1007291000/1008121000** **BETWEEN 1300-0200** TRIGGER NOTAM—PERM AIRAC AIP AMDT 2-10 WEF 29 JUL 2010 INCLUSION OF REMARK BETWEEN 1300 AND 0200 UTC ASIVO IS AVAILABLE ONLY AS AN EXIT POINT FOR NORTH BOUND OVERFLYING AIRCRAFT, FLIGHT LEVEL 340 OR ABOVE.
A0308-10	**10-07-22**	**MDSD / LAS AMERICAS INT'L AP** **1007221830/1009150400** RUNWAY 17/35 FRICTION COEFFICIENT IN THE FIRST THIRD MEASURED BELOW THE LEVEL SPECIFIED IN CIRCULAR CA 1400-03, PART 11.2.6, NUM (3), WILL BE CONSIDERED SLIPPERY SURFACE WHEN WET, CAUTION IS ADVISED, A COPY OF THIS CIRCULAR MAY BE DOWNLOADED FROM: HTTP://WWW.IDAC.GOV.DO/SEGURIDADOPE/CIRCULARES.HTM.
A0319-10	**10-07-30**	**MDSD / LAS AMERICAS INT'L AP** **1008021100/1008061700** **AUG 02 03 04 05 AND 06 1100-1700** TWY E-7 CLOSED DUE TO MEN AND EQUIPMENT WORKING.
A0320-10	**10-08-01**	**MDCS / SANTO DOMINGO FIR** **1008010000/1008312359 EST** CHECKLIST OF NOTAM SERIE ¨A¨ IN FORCE.
This List of Valid NOTAM cancel the last List of Valid NOTAM JULY 2010		